

**Zyxel WRE2205 v2  
V1.00(AANK.5)C0\_20171101  
Release Note**

Date: Nov, 24, 2017

**Support Platforms:**

Zyxel WRE2205 v2

**Versions:**

Firmware version: V1.00(AANK.5)C0\_20171101

**Notes**

This is a hotfix intended to resolve a specific problem before the standard solution firmware becomes available. Feel free to download it, but please be aware that this firmware has not gone through full software quality assurance testing. Only apply it to the devices that are experiencing the specific problem, and install the standard firmware when it becomes available.

**Production information**

1. Default IP :192.168.1.2
2. Default password :1234
3. Firmware upgrades may reset the repeater's configuration options to the factory default. Before performing an upgrade, please backup you current configuration first.

**Known Issues:**

None

**Modification in 1.00(AANK.5)C0\_21071101 | 11/24/2017**

[Bug Fix/ Change/ Enhancement]

1. Fix WPA2 KRACK vulnerability

**Modification in 1.00(AANK.5)C0 | 8/19/2015**

1. [Bug Fixed]

Fixed the issue of the one Connect on/off is not sync up between GUI and iPad apps issue.

### **Modification in 1.00(AANK.4)C0 | 6/25/2015**

1. [New Feature Support]

Support OneConnect 1.0.

- Support OneConnect AP-autoconfig.
- Support AP-autoconfig state change.
- Support WIFI power state control.
- Support set device reboot.

### **Modification in 1.00(AANK.3)C0 | 11/24/2014**

1. [Bug Fixed]

To fix the issue of connecting SSID manually.

### **Modification in 1.00(AANK.2)C0 | 7/2/2014**

1. [Bug Fixed]

To fix display issue on IE7/IE8.

2. [Bug Fixed]

To fix it would show nothing after loading different version firmware.

3. [Bug Fixed]

To fix the issue which empty can be accepted in RTS/CTS and Fragment features.

4. [Bug Fixed]

To fix the channel is not updating after connecting to upper AP.

5. [Bug Fixed]

To fix on showing wrong security information when upper AP's setting is in WPA2-PSK encryption.

6. [Bug Fixed]

To fix WPS led will flash in registrar on mac filter enabled during WPS process.

7. [Bug Fixed]

To fix that showing wrong IP address after connecting upper AP with encryption protocol on WEP.

### **Modification in 1.00(AANK.1)C0 | 10/24/2013**

1. [Bug Fixed]

To fix WPS connection issue with NBG4615V2.

**Modification in 1.00(AANK.0)C0 | 8/12/2013**

1. The first time firmware release.