

Zyxel Firmware Release Note

Model Name: WRE6606

Release Version: V1.00(ABDU.3)C0

Release Date: June 15, 2018

Notes

This is a hotfix intended to resolve a specific problem before the standard solution firmware becomes available. Feel free to download it, but please be aware that this firmware has not gone through full software quality assurance testing. Only apply it to the devices that are experiencing the specific problem, and install the standard firmware when it becomes available.

Product information

Default LAN IP: 192.168.1.2

Default password: 1234

Known Issues

1. Enable / disable 5G function will restart 5G interface. Eg. Enable MAC filter/ QoS/WPS/Scheduling
2. In Repeater mode: Lan setting change to static IP will disconnect 5G uplink about 10 sec. but recover to normal after 10 sec.
3. MAC filter does not work when WPS enable

Features

- Support MU-MIMO Wi-Fi
- AP/Client/Repeater modes
- One Connect support

Modification in V1.00(ABDU.3)C0 | Jun/15/2018

1. Fix the downlink SSID may be changed after second time WPS process, in repeater mode.

Modification in V1.00(ABDU.2)C0 | Mar/30/2018

2. Fix WPA2 KRACK vulnerability, official release
3. Fix Guest WLAN cannot be edited

Modification in V1.00(ABDU.1)C0 20171117 | Nov/24/2017

1. Fix WPA2 KRACK vulnerability

Modification in V1.00(ABDU.1)C0 | Mar/20/2017

1. Fix AP WPS LED not stop to success state when client linked up with WPS successfully.
2. Fix Device cannot login after change login password
3. Fix Device cannot auto change 2.4GHz wireless channel when upper router change channel.
4. Fix WebGUI "WLAN 2.4G Information" in Status page sometimes disappears.
5. Fix IE10 and IE11 have script error in Login page.
6. Fix Auto channel cannot select to a clear channel.
7. Fix Signal is weak when DUT is scanning in eaZy 123 Setup
8. Fix Sometime freeze when login WebGUI for 10~15 sec.

Modification in V1.00(ABDU.1)C0 | Sep/22/2016

First Release