

**ZyXEL WRE6505 Standard Version
Release V1.00(AAQB.5)C0_20171122
Release Note**

Date: Nov. 24, 2017

Supported Platforms:

WRE6505

Firmware Versions:

V1.00(AAQB.5)C0_20171122

Notes

This is a hotfix intended to resolve a specific problem before the standard solution firmware becomes available. Feel free to download it, but please be aware that this firmware has not gone through full software quality assurance testing. Only apply it to the devices that are experiencing the specific problem, and install the standard firmware when it becomes available.

Notes :

- 1. Default IP :192.168.1.2**
- 2. Default username : admin**
- 3. Default password :1234**
- 4. Firmware upgrades may reset the repeater's configuration options to the factory default. Before performing an upgrade, please backup you current configuration first.**

Known Issues :

N/A

Modifications in V1.00(AAQB.5)C0_20171122 | 2017/11/24

1. Fix WPA2 KRACK vulnerability

Modifications in V1.00(AAQB.5)C0 | 2017/10/05

1. Make the second SSID encrypted as default when SSID1 is enabled

Modifications in V1.00(AAQB.4)C0 | 2017/04/20

1. Disable Telnet

Modifications in V1.00(AAQB.3)C0 | 2016/04/20

1. 5G WiFi driver use v3.0.0.9
2. DFS is enabled in default

Modifications in V1.00(AAQB.2)C0 | 2015/10/23

1. [New Feature]: Support One Connect 2.0

zy1905 version	r6455
zy1905 suppose feature version:	
version	2.0
L2DeviveCtrl	701
WiFiAutoCfg	1001
WiFiOnOff	1101
FwUpgrade	1501

Modifications in V1.00(AAQB.1)C0 | 4/13/2105

1. [Bug Fixed]: fix Eth port disconnect issue when uplink AP changes radio (2.4G →5G or 5G →2.4G).
2. [Bug Fixed]: fix repeater auto IP issue when uplink AP is unreachable.
3. [Bug Fixed]: fix IoP issue with
 - ◆ Netgear R7500
 - ◆ Intel 6205 / Intel 7260
 - ◆ iPhone hotspot 5/5s (iOS 7.1.1/7.1.2) issue
 - ◆ Lenovo X220: Intel Advanced-N 6250
 - ◆ Lenovo X230: Intel Advanced-N 6250
 - ◆ Acer P633-M: Intel Advanced-N 6235
4. [Bug Fixed]: fix GUI issues on IE10/IE8
5. [Bug Fixed]: fix WMM issue
6. [Bug Fixed]: fix CHT MOD video issue
7. [Bug Fixed]: fix 1.00(AAQB.0)C0 reported bugs.

Modifications in V1.00(AAQB.0)C0 | 4/25/2014

Initial release